

Job Title: **Die Cast Furnace Loader**
Supervised By: Team Leader
Responsibility for directing others: None

Summary of Position: This position is responsible for loading aluminum ingot and scrap aluminum into multiple furnaces while maintaining the controls to consistently melt aluminum according to set standards.

Essential Job Duties:

- Load aluminum ingot and scrap aluminum into multiple furnaces per set standards.
- Coat ladles with compound to prevent sticking.
- Perform preventative maintenance and routine maintenance checks.
- Perform preventative maintenance and routine maintenance checks.
- Complete required paperwork.
- Must be able to move about in and around machinery and between lines.
- Frequently moves/lifts up to 50 lbs. throughout the shift.
- Constantly position self to run/maintain die cast machinery (stooping, bending, squatting, pushing, and pulling).
- Maintain 5S on multiple die cast machines.
- Withstand extreme temperatures (hot in summer, cold in winter).
- Ability to read and write the English language.
- Appropriate Personal Protective Equipment (PPE) must be worn in proper manner at all times.
- Ability to work varying shifts and overtime.